



# BARRE TONDE PIENE, LASTRE

## POM C

## PETP ARNITE

## POM C

Ø (mm)	Dimensioni (mm)	Dimensioni (mm)
5	3000	
6	3000	
8	3000	
10	3000	3000
12	3000	3000
15	3000	3000
18	3000	
20	2000 / 3000	2000 / 3000
22	2000 / 3000	
25	2000 / 3000	2000 / 3000
30	2000 / 3000	
35	2000 / 3000	2000 / 3000
40	2000 / 3000	
45	2000 / 3000	2000 / 3000
50	2000 / 3000	2000 / 3000
55	2000 / 3000	
60	2000 / 3000	2000 / 3000
65	2000 / 3000	2000 / 3000
70	2000 / 3000	2000 / 3000
75	2000 / 3000	2000 / 3000
80	2000 / 3000	2000 / 3000
90	2000 / 3000	2000 / 3000
100	2000 / 3000	2000 / 3000
110	2000 / 3000	2000 / 3000
120	2000 / 3000	2000 / 3000
125	2000 / 3000	
130	2000 / 3000	2000 / 3000
135	2000 / 3000	2000 / 3000
140	2000 / 3000	2000 / 3000
150	2000 / 3000	2000 / 3000
160	2000 / 3000	2000 / 3000
170	2000 / 3000	2000 / 3000
175	2000 / 3000	
180	2000 / 3000	2000 / 3000
190	2000 / 3000	2000 / 3000
200	2000 / 3000	2000 / 3000
210	1000	
220	1000	
230	1000	
240	1000	
250	1000	
260		
270		
280		
290		
300		
325		
350		
380		
400		
450		
500		

Spessore (mm)	Dimensioni (mm)
2	1000 X 2000
4	1000 X 2000
6	1000 X 2000
8	1000 X 2000, 620 X 2000
10	1000 X 2000, 620 X 2000
12	1000 X 2000, 620 X 2000
15	1000 X 2000, 620 X 2000
16	1000 X 2000, 620 X 2000
20	1000 X 2000, 620 X 2000, 1250 X 2500
25	1000 X 2000, 620 X 2000, 1250 X 2500
30	1000 X 2000, 620 X 2000, 1250 X 2500
35	1000 X 2000, 620 X 2000, 1250 X 2500
36	1000 X 2000, 620 X 2000, 1250 X 2500
40	1000 X 2000, 620 X 2000, 1250 X 2500
45	1000 X 2000, 620 X 2000, 1250 X 2500
50	1000 X 2000, 620 X 2000, 1250 X 2500
60	1000 X 2000, 620 X 2000
80	620 X 2000
100	620 X 2000